

		70°40'0"W	70°30'0"W	70°20'0"W
41°00"N			A A A A A A A A A A A A A A A A A A A	Met Buoy #2 (NE Corner)
				Current Mooring #2 (NE Corner)
40°50'0'N				
	A Met Buoy			
	#1 (SW Corner)			
40°40'N	#1 (SW Corner)			
		A A A A A 6 8 10 Miles		
	0 1 2 4	6 Nautical Miles	A A A A A A NAD 83 (2011) U A 0520	
		Name Easting(NAD83 un   Current Mooring #1 (SW Corner) 357328.2   Current Mooring #2 (NE Corner) 383860.9   LiDAR Buoy 370744.2   Met Buoy #1 (SW Corner) 358280.3	ma19N) Northing(NAD93.utma19N) 4507410.4 4533443.3 4520828.8 4508362.8	Longbitude wgs84 Lstitude WGS84 Depth   70* 41* 19,988* W 40* 42* 18,962* N -61   70* 23* 8,481* W 40* 56* 37,728* N -42   70* 31* 58,456* W 40* 49* 41,949* N -53   70* 41* 09,026* W 40* 42* 50,428* N -59


Hello Elizabeth,

Please be informed RPS Group, Inc. will be servicing Beacon Wind's metocean buoys in November 2022. Offshore supply vessel, **Berto L. Miller (MMSI 338454000) or Josephine K. Miller (MMSI 367506560),** dependent on vessel availability, will be conducting the servicing at the metocean facilities. The service visit is being planned for November 6th-12th 2022. **Metocean buoy #2 will be decommissioned and removed from the water.** 

## **Berto L. Miller**



Josephine K. Miller



Fisheries questions: Please contact Elizabeth Marchetti at <u>emarc@equinor.com</u>



